


ISSUE with: 2 x GTX TITAN Z's on a MSI X99S Gaming 9 Motherboard - System should also read 4 x GPU's



The Plastic support clips at the bottom of the ram module bays.

PCI_E - Lane 1


MSI X99S Gaming 9 AC

Issue:

Part 1 & 2 are colliding by a max. of 1.5mm and this will not allow for the GPU to be correctly seated on the X99S Gaming 9 Motherboard.

Situation:

2 x GTX Titan Z will not fit on this motherboard without a modification required to either the GTX Titan Heat Sink or the Plastic Support Brackets for the Ram modules.



PART 2

The height of the Heatsink

GTX Titan Z



System with Cooler Masters Cosmos 2 Case